

1. Optional: Secure the Bracket to the counter with two screws (not included).
2. Optional: Drill a hole (if needed) through which to route cables.
3. Attach the Mount to the Bracket using the screws provided at one of the two height settings.
4. Tilt the scanner as shown and snap it into place in the Bracket, making sure the cables are not pinched or kinked.
5. Route the cables to their proper connections.
6. To remove the scanner from the Mount, lift it directly upwards rather than tilting.

